VZCZCXRO8997
PP RUEHROV
DE RUEHROV #0108 1920923
ZNR UUUUU ZZH
P 110923Z JUL 07
FM AMEMBASSY VATICAN
TO RUEHC/SECSTATE WASHDC PRIORITY 0766
INFO RUEHRO/AMEMBASSY ROME PRIORITY 0117
RUEHROV/AMEMBASSY VATICAN 0796

UNCLAS VATICAN 000108

SIPDIS

SIPDIS

DEPT. FOR OBO/OM/AM/EUR KENNETH PARENT, RICHARD FULCHER OBO/PE/SM/TSB; ROME FOR RSO, GSO, FM

E.O. 12958: N/A TAGS: ABLD AMGT ASEC

SUBJECT: FE/BR WINDOW REPLACEMENT

REF: A. E-MAIL PARENT(OBO)/FULCHER(OBO/PE/SM/TSB) 12/13/2006

- - TC. E-MAIL GANSER (VATICAN)/ FULCHER (OBO/PE/SM/TSB) 02/13/2007
 - 1D. E-MAIL FULCHER(OBO/PE/SM/TSB)/ GANSER (VATICAN) 02/17/2007 1E. E-MAIL GANSER (VATICAN)/ FULCHER(OBO/PE/SM/TSB) 03/12/2007
 - 1F. E-MAIL PARENT(OBO)/FULCHER, BEST(OBO/PE/SM) 4/19/2007
 - G. TELECON GANSER (VATICAN)/ FULCHER, BEST(OBO/PE/SM) 7/6/2007
- 11. The FE/BR windows installed in the ground floor of the Vatican Chancery are deteriorating and three of the thirteen panels have already suffered fogging damage which limits the visibility and light entering through the panels. The FE/BR panels, which were installed in 1993/1994, are reaching the end of their serviceable life. Per reftels, Post requests OBO/PE/SM assess and schedule Post's FE/BR panels for replacement.
- 12. Embassy Vatican POC is Mgmt Officer Peter Ganser. This request was coordinated with OBO Area Manager Kenneth Parent.

SANDROLINI